# **Inspection and Maintenance Assessment**

## Care, Street, City, OO, Zip



**Inspector** Joe Smith

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

©1996-2010 Page 1 of 9

## **Inspection and Maintenance Assessment For**

G = Good, F = Fair, P = Poor, N/A = Not Applicable

	CONDITION OF NEIGHBORHOOD:	G	F	Р	N/A	Comments
1)	Overall condition of neighborhood		X			The building is on a rural main road with a restaurant in front of it and a magistrates office to the side. The main entrance of this building faces the rear of the restaurant. There is an abandoned trailer in the rear yard and several dumpsters.
	CURB APPEAL OF REFERENCED PROPERTY:					
2)	Overall first impressions of this property	Х				
3)	Landscaping	Χ				
4)	Irrigation				Χ	
5)	Driveway approach	Χ				
6)	Trash enclosure/refuse container	Χ				
7)	Fencing	Х				
	SITE:					
8)	Site paving	Х				
9)	Parking space striping	Х				
10)	Handicapped parking identified	Х				
11)	Curbing/sidewalks	Х				
12)	Ingress/egress	Х				
13)	Site lighting	Х				
14)	Storm drainage	Х				

#### " Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 2 of 9

#### FORM 2

G = Good, F = Fair, P = Poor, N/A = Not Applicable

	BUILDING EXTERIORS:	G	F	Р	N/A	Comments
15)	Exterior surfaces/siding	Χ				
16)	Trim/paint	Χ				
17)	Exterior lighting (building mounted)	Х				
18)	Windows and doors	Χ				
19)	Exterior entryways	Χ				
20)	Stairs/railings/balconies				Х	
21)	Signage	Х				
	BUILDING ROOFS:					
22)	Overall condition of roofing material (if accessible)	Х				The roof is a metal roof and I was unable to walk on the roof.
23)	Gutters/flashing/downspouts	Χ				
24)	Skylights				Х	
25)	Parapet walls	Χ				
26)	Exterior HVAC units (roof or pad mounted)				Х	Rust from leak under the unit closest to the main road.
	INTERIOR COMMON AREAS:					
27)	Lobby/reception area	Χ				
28)	Kitchen/break room areas	Χ				
29)	Restrooms	Х				
30)	Halls/stairways	Х				
31)	Doors/windows	Х				
32)	Walls/ceilings	Х				
33)	Painting	Х				
34)	Lighting	Х				
35)	Emergency lighting	Х				
36)	Floor coverings	Χ				

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 3 of 9

#### FORM 3

G = Good, F = Fair, P = Poor, N/A = Not Applicable

	INTERIOR MECHANICAL SYSTEMS	G	F	Р	N/A	Comments
	(Visual inspection)					
37)	HVAC			Х		Rust under front roof top unit.
38)	Electrical	X				
39)	Plumbing/water heaters	Х				
40)	Fire suppression	Х				
41)	Security system	Х				
42)	Vertical transportation (elevator/escalator)				Х	
	TENANT SPACES:					
43)	Doors/windows	Х				
44)	Walls/ceilings	Х				
45)	Painting	Х				
46)	Lighting	Х				
47)	Emergency lighting	Х				
48)	Floor coverings	Х				
49)	Separate computer/data room Yes No	Х				Yes this room is present.

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 4 of 9

#### **Visuals and Pictures**

### Care, Street, City, OO, Zip

1



Front Entrance

3



Left Side

5



Street side

2



Rear

4



Side facing main street with dumpster and entrance

6



Generator with soot marks on the side

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 5 of 9

7



Utility box

9



Front entrance

11



Handicap parking spots

8



Front Entrance

10



Building to the right of property

12



Vent dislodged in foyer


" Independently Owned and Operated "

Inspection Date : Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800


©1996-2010 Page 6 of 9

13



Fire protection inside front door

15



Waiting room area

17



Bathroom in waiting area

14



Emergency beacon

16



Hall to patient area

18



Kitchen for employees

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 7 of 9

19

21

23



Roof and package units



Roof penetration and gutter

20



HVAC

22



Roof

24



Dumpster area

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

Inspector Phone: (281) 394-5800 9/30/2010

Page 8 of 9 ©1996-2010

25



Exterior

27



Generator

26



Generator

28



Sign at street

" Independently Owned and Operated "

Inspection Date: Inspector: Joe Smith

9/30/2010 Inspector Phone: (281) 394-5800

©1996-2010 Page 9 of 9